# Corning's new innovative packaging solution for jumpers is now available!

What are the features?
- Holds up to 70 jumpers, up to 20 m long
- Self-tracking inventory system

What is the value?
- Improved inventory management
- Lower risk of stock out and easier recognition for reorder
- User-friendly and time-saving features enabling higher workplace efficiency

Part number identification at a glance	Self-tracking inventory count on each bag	Colored bar indicating single-mode or multimode

Quick Order Guide

Part Number	Description
7979-OM4-B70-01M	LC PC Uniboot, multimode (OM4), 70 jumpers, 1 m
7979-OM4-B70-02M	LC PC Uniboot, multimode (OM4), 70 jumpers, 2 m
7979-OM4-B70-03M	LC PC Uniboot, multimode (OM4), 70 jumpers, 3 m
7979-OM4-B70-04M	LC PC Uniboot, multimode (OM4), 70 jumpers, 4 m
7979-OM4-B70-05M	LC PC Uniboot, multimode (OM4), 70 jumpers, 5 m
7878-OS2-B70-02M	LC UPC Uniboot, single-mode Corning® ClearCurve®, 70 jumpers, 2 m
7878-OS2-B70-03M	LC UPC Uniboot, single-mode Corning ClearCurve, 70 jumpers, 3 m
7878-OS2-B70-05M	LC UPC Uniboot, single-mode Corning ClearCurve, 70 jumpers, 5 m

Don't see what you need in the quick order guide?
Configure your jumper in a box to suit your needs!

|1 |2 |3 |4

|1
Select connector code.
Multimode
7979 = LC PC uniboot
Single-mode
7878 = LC UPC uniboot

|2
Select fiber type.
OM4 = Multimode
OS2 = Single-mode
Corning ClearCurve

|3
Length determines quantity.
B70 = 1-5 m
B50 = 6-10 m
B40 = 11-15 m
B30 = 15-20 m

|4
Select assembly length.
01M - 20M = 1-20 m
01F - 70F = 1-70 ft

For more information, visit www.corning.com/opcomm or contact Customer Care at 800-743-2675.